

Learning the lessons from bridge collapses around the world

Mungo Stacy

Principal Engineer, Parsons Brinckerhoff

"Failure is central to engineering ... every single calculation that an engineer makes is a failure calculation.

Successful engineering is all about understanding how things break or fail."

Henry Petroski

Tay bridge – 28 Dec 1879




Tacoma Narrows – 7 Nov 1940



Milford Haven – 2 June 1970



Ynys-y-gwas – 4 Dec 1985



MacArthur Maze – 29 Apr 2007



Cameroon – 1 July 2004



Montreal – 30 Sept 2006



Minnesota – 1 Aug 2007



Fenghuang, China - 14 Aug 2007



Can Tho, Vietnam – 26 Sept 2007



I35E Minnesota – 26 July 2008



Czech republic – 8 Aug 2008



Delhi Metro – 20 Oct 2008



Minnesota – 15 Nov 2008



Hanoi, Vietnam – 10 Mar 2009



Zhuzhou, China – 17 May 2009



Kerry – 7 Feb 2007




Ludlow – 26 June 2007



Shropshire – 22 Oct 2008



Selby - 2001



Gerrards Cross – 30 June 2005



Millennium Bridge – 12 June 2000



Liverpool St GE19 – 28 May 2008



Clyde Arc – 14 Jan 2008



Learning the lessons from bridge collapses



Minnesota
*I35W Highway
bridge*

Built
1967

Collapsed
Aug 2007




Montreal
*de la Concorde
overpass*


Built
1971

Collapsed
Sept 2006









Bridge owning agency

“...recognised nationally and internationally as a leading Transportation Agency and a model for both the nation and other countries”

“...consulted by several European countries regarding best practices”

Bridge owning agency

“...from fiscal year 2001 to 2007, the number of Department staff declined by 19%”

“...departure of professional staff, particularly senior engineers”

“The Department and other similar departments around the county have lost engineers to more lucrative or interesting positions in the private sector”

Bridge owning agency

“...various organisational structures during the years since its creation...”

“...many people commented on the low moral that currently exists in the Department...”

“...the agency has lost substantial administrative infrastructure support, which has placed a greater burden on the professional staff to perform administrative and clerical tasks”

Inspections

Form 17108 (12-71)

Minnesota Department of Highways

1972 BRIDGE INSPECTION REPORT

Prepare 4 copies:
 Original to District Engineer
 First copy to Area Maintenance Engineer
 Second & Third copies to Central Operations

Bridge No. 9340	Check One: <input checked="" type="checkbox"/> annual inspection <input type="checkbox"/> special inspection	Date 11-29-72	Year Built 1967
Maintenance Area 5A	T. H. No. 35W	Mile Post 18.43	Location 2 Mi. N. of I94
Type B.S. & 3 Slab Spans	<input checked="" type="checkbox"/> Over <input type="checkbox"/> Under	Miss. Rv. & Rwy.	Bridge Posted For _____ Tons

I	ITEM	RATING	COMMENTS AND SKETCHES <small>Refer to item number in comments and sketches Use additional sheets if necessary</small>
	Substructure	8	(10) The south expansion hinge should be checked for excessive expansion at 90° or higher.
1	Footings		
2	Abutments	8	(11) Light rusting under the open hinge joints.
3	Wing Walls	8	
4	Piers	8	(12) The joints at the cover plates are leaking. 500 L.F. of the 1 st median joint has fallen out.
5	Bridge Seats	8	
	Superstructure	7	(14 & 15) N.B.L. has been sealed but 800 L.F. of add'l cracks should be sealed and 8,000 L.F. of leaking transverse cracks in the S.B.L. should be sealed.
6	Trusses	8	
7	Girders	8	
8	Floor Beams	8	(17) Drains over the south bank are plugged and need cleaning. (Sand gets trapped in the horis. troughs.
9	Stringers	8	
10	Bearing Devices	8	
11	Paint (Yr. Ptd. 1968)	7	
	Decks	7	
12	Expansion Joints	7	
13	Railing	8	
14	Structural Slab		
15	Wearing Surface		
16	Curb & Walk		
	Drains	7	
	Channel & Protection	8	
18	Area Under Bridge	8	
19	Stream Bed		
20	Slope Protection	8	
	Culverts		
21	Barrel & Floor		
22	Apron Wing Wall		
23	Retaining Wall		

Condition rating from 9 (very good) to 0 (very poor) for condition noted
 Rating of 9 ---- new condition
 Rating of 8 ---- good condition - no repair necessary
 Rating of 7 ---- some minor damage to need of repair by maintenance forces

Date: 11-29-72

Date: 11-29-72

Form 17108A (1-74)

Minnesota Department of Highways
 BRIDGE INSPECTION REPORT

Original to Area Maintenance Engineer
 First copy to Bridge Maint. Supt.
 Second copy to Bridge Inventory Group

Bridge No. 9340 S' 9340A	T.H. No. 35W	Mile Post 18.5A	Location 0.5 MI. N.D. OF JCT. TW. 12	Maintenance Area 5A
Type (104) 11 WIDE SPANS 3 CONT. ST. DL. TRUSS	<input checked="" type="checkbox"/> Over <input type="checkbox"/> Under	MISS. RIVER	Posted Limit in Tons	<input checked="" type="checkbox"/> annual inspection <input type="checkbox"/> special inspection

I	ITEM	RATING	COMMENTS AND SKETCHES <small>Refer to item number in comments and sketches Use additional sheets if necessary</small>
	Substructure	6 6 6 6	1) SO. ABUT. BRIDGE SEAT - CRACKING AND DISCOLORED.
1	Abutments	7 7 7 7	
2	Piers	6 6 6 6	2) PIER 7 (FIXED PIER ON N.E. EDGE OF RIVER) WEST COLUMN IS CRACKED VERTICALLY COMPLETELY THROUGH COLUMN.
	Superstructure	7 7 7 7	3) SMALL AREAS OF SEVERE CORROSION OCCURRING, ESPECIALLY UNDER MEDIAN JOINT AND A SMALL AMOUNT OF CORROSION ON LOWER WOOD (EAST) JUST SOUTH OF PIER 8.
3	Trusses	7 7 7 7	
4	Girders	N N N N	4) SOME OF THE JOINTS TOO TIGHT.
5	Floor Beams	7 7 7 7	
6	Stringers or Beams	8 8 8 8	5) DIET & DEBBEL UNDER COLLIER BEARINGS - NO INDICATION THAT BEAS ARE MOVING AS MUCH AS DESIGNED TO MOVE.
7	Bearing Devices	7 7 7 7	6) 15-20% OF CONC. RAIL BASE IS UNSOUND.
	Decks	6 6 6 6	7) 200-200 L.F. OF TRANSVERSE DECKS IN LOW SWAMP OVERLIES -
8	Expansion Joints	7 7 7 7	8) FACE OF CURB STARTING TO SPALL IN SPOTS.
9	Railing	6 6 6 6	9) SEE 8) ABOVE - MAY BE A PAVEMENT PRESSURE PROBLEM.
10	Structural Slab	8 7 6 6	10) NO HAZARD MARKERS
11	Wearing Surface	7 7 7 7	11) 4-5% PAINT UNSOUND
12	Curb & Walk	7 7 7 7	12) DRAINS PERMANENTLY PLUGGED -
	Area Under Bridge	8 8 8 8	
13	Channel & Protection	8 8 8 8	
14	Roadway, Railway, Other	8 8 8 8	
15	Slopes & Berms	8 8 8 8	
	Culverts	N N N N	
16	Barrel & Floor	N N N N	
17	Apron & Wings	N N N N	
	Other	7 7 7	
18	Retaining Wall	N N N	
19	Approaches	7 7 7 7	
20	Signing	7 7 7 7	
21	Paint (yr. ptd.) 1968	7 7 7 7	
22	Drainage	7 7 6 6	
23	Guard Rail #5	8 8 8 8	
24	CONDUIT	8 8 8 8	
25			

INSPECTED BY: [Signature]
 Date: 5/17/84

Date: 6/14/82	Date: 5/17/83	Date: 5/17/84	Date: 11/7/85
---------------	---------------	---------------	---------------

Inspections

Form 17108 (12-71)

Minnesota Department of Highways

1972 BRIDGE INSPECTION REPORT

Prepare 4 copies:
 Original to District Engineer
 First copy to Area Maintenance Engineer
 Second & Third copies to Central Operations

Bridge No. 9340	Check One: <input checked="" type="checkbox"/> annual inspection <input type="checkbox"/> special inspection	Date 11-29-72	Year Built 1967
Maintenance Area 5A	T. H. No. 35W	Mile Post 18.43	Location 2 Mi. N. of I94
Type B.S. & 3 Slab Spans	<input checked="" type="checkbox"/> Over <input type="checkbox"/> Under MISS. Rv. & Rwy.	Bridge Posted For	Tons

I	ITEM	RATING	COMMENTS AND SKETCHES <small>Refer to item number in comments and sketches Use additional sheets if necessary</small>
	Substructure	8	(10) The south expansion hinge should be checked for excessive
1	Footings	8	
2	Abutments	8	(11) Light
3	Wing Walls	8	(12) one joint
4	Piers	8	500 L.F. of th
5	Bridge Seats	8	(14 & 15) N.B. of ad'l crack of leaking tr should be sea.
6	Superstructure	7	
7	Trusses	8	
8	Girders	8	
9	Floor Beams	8	(17) Drains need cleaning troughs.
10	Stringers	8	
11	Bearing Devices	8	
12	Paint (Yr. Ptd. 1968)	7	
DECKS			
13	Expansion Joints	7	
14	Railing	8	
15	Structural Slab		
16	Wearing Surface		
17	Curb & Walk		
18	Drains	7	
19	Channel & Protection	8	
20	Area Under Bridge	8	
21	Stream Bed		
22	Slope Protection	8	
CULVERTS			
23	Barrel & Floor		
24	Apron Wing Wall		
25	Retaining Wall		
26			
27			
Inspected	Date: 11-29-72		

Condition rating from 9 (very good) to 0 (very poor) for conditions noted
 Rating of 9 --- new condition
 Rating of 8 --- good condition - no repair necessary
 Rating of 7 --- minor items in need of repair by maintenance forces
 Rating of 6 --- major items in need of repair by maintenance forces
 Rating of 5 --- major repair needed to be set
 Rating of 4 --- minimum adequacy to tolerate present traffic - immediate rehabilitation necessary to keep open
 Rating of 3 --- inadequacy to tolerate present heavy load - warrants closing bridge to trucks
 Rating of 2 --- inadequacy to tolerate any live load - warrants closing bridge to all traffic
 Rating of 1 --- bridge repairable, if desirable to reopen to traffic
 Rating of 0 --- bridge conditions beyond repair - danger of immediate collapse
 Place dash where item is not rated

Form 17108A (1-74)

Minnesota Department of Highways

BRIDGE INSPECTION REPORT


Original to Area Maintenance Engineer
 First copy to Bridge Maint. Supt.
 Second copy to Bridge Inventory Group

Bridge No. 9340 5' 9340A	T.H. No. 35W	Mile Post 18.54	Location 0.5 MI. N.W. OF JCT. TW. 12	Maintenance Area 5A
Type (104) 11 ARA SPANS 3 CONT ST. DK TRUSS	<input checked="" type="checkbox"/> Over <input type="checkbox"/> Under MISS. RIVER	Posted Limit in Tons	<input checked="" type="checkbox"/> annual inspection <input type="checkbox"/> special inspection	



I	ITEM	RATING	COMMENTS AND SKETCHES <small>Refer to item number in comments and sketches Use additional sheets if necessary</small>
	Substructure	6 6 6 6	1) SO. ABUT. BRIDGE SEAT - CRACKING AND DISCOLORED.
1	Abutments	7 7 7 7	
BRIDGE SEATS			
	Superstructure		
6	Trusses	8	(16) E.G. OF RIVER) MED VERTICALLY IN COLLUMN. SEE DISSECTION UNDER MEDIAN AMOUNT OF DISCOLORED (EAST) - 8
7	Girders	8	DO TIGHT. OR ROLLER LICATION THAT MUCH AS DESIGNED
8	Floor Beams	8	TAIL BASE IS
9	Stringers	8	(TRANSVERSE DECKS DELAY - STARTING TO SPALL
10	Bearing Devices	8	BY BE A PAVEMENT
11	Paint (Yr. Ptd. 1968)	7	AND PLUGGED. -
21	Paint (yr. ptd.) 1968	7 7 7 7	2) NO CHANGE. THE HIG. JAPS THE BRIDGE - TAB SPANS ARE
22	Drainage	7 7 6 6	3) CLEANING OUT OF THE RETAINING SLAB IN SEVERAL PLACES (NORTH END OF BRIDGE)
23	Guard Rail #5	8 8 8 8	4) BOTTOM OF SLAB CURBING & MEDIAN DETECTOR - MISSING IN MANY PLACES - ESPECIALLY WEST END
24	CONDUIT	8 8 8 8	
25			
ESTIMATED COST OF REPAIR (1972)			
	Labor	Material	Equipment Total By Engineer
Inspected by	Date: 5/17/84		
	Date: 11/7/85		

Bridge condition - superstructure

◆ Superstructure condition rating




Bridge condition - status



Inspections – fracture critical

Fracture Critical Bridge Inspection Report



*Bridge # 9340
I-35W over the Mississippi River
(Downtown Minneapolis)*


September 1998



*Minnesota Department of Transportation
Bridge Inspection, Maintenance Operations
Metro Division*

Inspections – fracture critical

Fracture Critical Bridge Inspection Report



*Bridge # 9340
I-35W over the Mississippi River
(Downtown Minneapolis)*

September 1998



*Minnesota Department of Transportation
Bridge Inspection, Maintenance Operations
Metro Division*

1994: Bridge classed as 'fracture critical' and 'non-load-path-redundant'

Failure of critical member expected to result in collapse of bridge

Fatigue / redundancy studies





Figure 7: Gaged Locations on the Main Truss

Physical testing and modelling conducted by University of Minnesota



"Budget Buster"

Major TH Bridges Requiring Replacement or Renovation in the Next 10 Years

D7	TH 169/Minnesota at Le Sueur	2005
Metro	TH 36/St Croix at Stillwater	2007
D2	TH 11/Red River at Robbin	2008
Metro	TH 52/Mississippi in St Paul - Lafayette	2010
D6	I90/Mississippi at Dresbach	2010
Metro	I 35E/Cayuga St & RR in St Paul	2010
Metro	I35W/Mississippi in Minneapolis	2012
Metro	TH 61/Mississippi at Hastings	2014

“Without warning”?

- ‘Structurally deficient’ status since 1991
- Identified as fracture critical and non-load-path-redundant
- Extensive studies carried out on fatigue and redundancy
- Identified for replacement as a ‘budget buster’

“Without warning”?

- ‘Structurally deficient’ status since 1991
- Identified as fracture critical and non-load-path-redundant
- Extensive studies carried out on fatigue and redundancy
- Identified for replacement as a ‘budget buster’
- No improvement to ‘deficient’ rating over 16 years despite work and studies on structure


Investigations




Inspection reports - 2004

Panel Point #13 (East Truss):

Water from deck drains fall directly into river. [99/2002] Bottom chord gusset plate has section loss, flaking & pack rust. [1999] Truss bottom chord member L13/L14 has cracked tack welds at two interior stiffeners. [2004] Bottom chord member L13/L14 cracked tack weld @ diagram tab (diagram #1?). Cracked tack weld @ diagram tab member L13/U14 see photos.



Bottom Chord Connection Condition




2004 Bridge Inspection
Bridge #9340


-23-

Inspection reports - 2004

Panel Point #13 (East Truss):
Water from deck drains fall directly into river. [99/2002]
Bottom chord gusset plate has section loss, flaking & pack rust. [1999] Truss bottom chord member L13/L14 has cracked tack welds at two interior stiffeners. [2004] Bottom chord member L13/L14 cracked tack weld @ diagram tab (diagram #1?). Cracked tack weld @ diagram tab member L13/U14 see photos.



Bottom Chord Connection Condition



Member L13/L14 Cracked Tack Weld



Member L13/U14 Cracked Tack Weld

Panel Point #13 (East Truss):
Water from deck drains fall directly into river. [99/2002]


Bottom chord gusset plate has section loss, flaking & pack rust.

[1999] Truss bottom chord member L13/L14 has cracked tack welds at two interior stiffeners. [2004] Bottom chord member L13/L14 cracked tack weld @ diagram tab (diagram #1?). Cracked tack weld @ diagram tab member L13/U14 see photos.


Inspection reports - 2005

Panel Point #13 (East Truss):

Water from deck drains fall directly into river. [9/9/2002] Bottom chord gusset plate has section loss, flaking & pack rust. [1999] Truss bottom chord member L13/L14 has cracked tack welds at two interior stiffeners. [2004] Bottom chord member L13/L14 cracked tack weld @ diagram tab (diagram #1?). Cracked tack weld @ diagram tab member L13/U14 see photos.



Bottom Chord Connection Condition




Member L13/L14 Cracked Tack Weld




Member L13/U14 Cracked Tack Weld

Panel Point #13 (East Truss):


Water from deck drains fall directly into river. [9/9/2002] Bottom chord gusset plate has section loss, flaking & pack rust. [1999] Truss bottom chord member L13/L14 has cracked tack welds at two interior stiffeners. [2004] Bottom chord member L13/L14 cracked tack weld @ diagram tab (diagram #1?). Cracked tack weld @ diagram tab member L13/U14 see photos.



Condition @Bottom Chord Connection



Member L13/L14 Cracked Tack Weld




2005 Bridge Inspection
Bridge #9340

-23-


Inspection reports - 2006

Panel Point #13 (East Truss):

Water from deck drains fall directly into river. [99/2002] Bottom chord gusset plate has section loss, flaking & pack rust. [1999] Truss bottom chord member L13/L14 has cracked tack welds at two interior stiffeners. [2004] Bottom chord member L13/L14 cracked tack weld @ diagram tab (diagram #1?). Cracked tack weld @ diagram tab member L13/U14 see photos.



Bottom Chord Connection Condition



Member L13/L14 Cracked Tack Weld



Member L13/U14 Cracked Tack Weld

METRO DISTRICT MAINTENANCE

2004 Bridge Inspection
Bridge #9340 -23-

Panel Point #12 (East Truss):


[1999] Truss bottom chord member L12/L13 has a cracked tack weld at an interior stiffener. [2004] Ground out pit from past inspection.




Weld Ground Out

Panel Point #13 (East Truss):

Water from deck drains fall directly into river. [1999] Truss bottom chord member L13/L14 has cracked tack welds at two interior stiffeners. [99/2002] Bottom chord gusset plate has section loss, flaking & pack rust. [2004] Bottom chord member L13/L14 has cracked tack weld @ diagram tab. Cracked tack weld at diagram tab member L13/U14. See photos. [2006] Bottom chord member L13/L14 has a missing bird cover.



Condition @ Bottom Chord Connection



Member L13/U14 Cracked Tack Weld

METRO DISTRICT MAINTENANCE

2006 Bridge Inspection
Bridge #9340 -24-

2006 Bridge Inspection
Bridge #9340

-24-

Global analysis



Minneapolis I-35W Bridge

← North-

U10'

U10

Pier 7

L11'


L11

Pier 6


Mississippi River

987 feet


N A T I O N A L T R A N S P O R T A T I O N S A F E T Y B O A R D




Gusset plate FE model




Gusset plate U10W - 2003




Gusset plate U10W - 2003





North

Pre-Collapse



North

L11W

Collapse Video - Frame #1



North


L11W

Collapse Video - Frame #2

North

L11W


Collapse Video - Frame #3



North


L11W

Collapse Video - Frame #4




North

Collapse Video - Frame #5




North

Collapse Video - Frame #6




North


Collapse Video - Frame #7



North

Collapse Video - Frame #8






North

Collapse Video - Frame #9

North

Collapse Video - Frame #10



North



Collapse Video - Frame #11

Probable cause

Accident report determined cause to be:

- inadequate load capacity of the gusset plates at the U10 nodes
- due to design error

Failure occurred under combination of:

- substantial weight increases due to bridge modifications
- concentrated construction loads

“Without warning”?

Bridge owner concerned about:


- ‘Structurally deficient’ condition rating
- Fatigue cracking

These factors did not contribute to the collapse

Assumptions on gusset plates

The bridge designer (design checker):


“...joints are typically stronger than the members they connect ... believe the detailer was a relatively new employee”



Assumptions on gusset plates

The bridge inspector:


“...that’s fit up, that’s original construction ... the reason we made that determination is, one, from me from undergrad, gusset plates are overdesigned. The factor safeties within those gusset plates are 2 to 3.”



Assumptions on gusset plates

The standards writers:


“...the AASHTO Guide for Commonly Recognized Structural Elements does not include gusset plates as a bridge structural element requiring specific attention and subsequent condition rating during bridge inspections.”



Assumptions on gusset plates

The software writers:


“...commonly used computer programs for load rating analysis do not include gusset plates ... the resulting load ratings might not accurately reflect the actual capacity of the structure.”



Assumptions on gusset plates

The bridge owner:

“...because bridge owners generally consider gusset plates to be designed more conservatively than the other members of a truss ... bridge owners typically ignore gusset plates when performing load ratings”



Learning from failure

Federal Highway Administration issues technical advisory (15 Jan 2008). Gusset plate capacity to be checked on non-load-path-redundant truss bridges:

- for new/replacement bridges during initial load rating
- for future load rating calculations for changes in condition or dead load
- review previous calculations for bridges subject to significant changes in stress levels

Grand River Bridge, Ohio

- Gusset plates buckled on 24 May 1996
- Construction traffic parked on bridge
- Gusset plate thickness inadequate



Learning from failure?



- Bridge repaired with thicker gusset plates
- Importance of inspecting gusset plates emphasised in Ohio bridge inspector training
- Article in Sept 1997 Civil Engineering magazine



Boulevard de la Concorde overpass, Montreal











Failure in thick slab

Half-joint intact





N

N

N

105





CNEI-65

a)

Causes - poor anchoring detail

Reinforcement detailing:


- not in accordance with best practice
- inadequately anchored
- but did not contravene 1966 code



Causes - misplaced reinforcing bars

As-built reinforcement:

- hanger bars misplaced
- created unreinforced zone of weakness



Contributory physical causes

- Absence of shear reinforcement in thick slab
- Absence of proper waterproofing
- Damages induced by repair work



Inspections

“the inspection reports ... show significant deficiencies and are not compliant with the manuals”

Montreal Commission of Inquiry

Inspections

“the inspection reports ... show significant deficiencies and are not compliant with the manuals”

Montreal Commission of Inquiry

“MnDOT did not follow its own policies with respect to documenting the deteriorating condition of the bridge”

Minnesota Legislature Investigative Report

Repair work – Feb 1992



b

'92 3 8

Special inspection – 15 July 2004



Inspection – day of collapse



UK infrastructure



Bridge management issues

“...numerous file-keeping flaws in the case of the de la Concorde overpass”

Bridge management issues

“...numerous file-keeping flaws in the case of the de la Concorde overpass”

“The absence of a complete file accessible to the ...inspectors ... was a key factor that contributed to the lack of follow-up on the progressive deterioration of the overpass”

Bridge management issues

“...numerous file-keeping flaws in the case of the de la Concorde overpass”

“The absence of a complete file accessible to the ...inspectors ... was a key factor that contributed to the lack of follow-up on the progressive deterioration of the overpass”

“...many opportunities were missed throughout the years to investigate in detail the condition of the structure”

Montreal Commission of Inquiry

Vulnerable structures

Montreal: Thick slabs without shear reinforcement

Minnesota: Gusset plates / non-load-path-redundant

“...the *Ministère* must better identify the structures that are at risk and award them special status in the management system”

Montreal Commission of Inquiry

Design approval

“...the *Ministère* approved the preliminary design ... without anticipating the considerable difficulties that would result ... it did not assess the inspection problems that such a structure might involve”

Design approval

“...the *Ministère* approved the preliminary design ... without anticipating the considerable difficulties that would result ... it did not assess the inspection problems that such a structure might involve”

“The Commission recommends that any mandate for structural design should specifically be validated (verification of designer’s concept, drawings and calculations)”

Montreal Commission of Inquiry

Recommendation 6

Design approval

“Develop and implement ... a bridge design quality assurance / quality control programme ... that includes procedures to detect and correct bridge design errors before the design plans are made final; and, at a minimum, provides a means for verifying that the appropriate design calculations have been performed, that the calculations are accurate...”

*National Transportation Safety Board
Recommendation H-08-17*

Technical approval

	TA prevent?
Poor anchoring detail of top bars	
Misplacement of bars	
Concrete not durable	
Absence of shear reinforcement	
Absence of proper waterproofing	
Damages induced by repair work	
Use of half-joints	

Technical approval

	TA prevent (1968)?
Poor anchoring detail of top bars	✓
Misplacement of bars	
Concrete not durable	✓
Absence of shear reinforcement	
Absence of proper waterproofing	
Damages induced by repair work	N/A
Use of half-joints	

Technical approval

	TA prevent (1968)?
Poor anchoring detail of top bars	✓
Misplacement of bars	×
Concrete not durable	✓
Absence of shear reinforcement	×
Absence of proper waterproofing	×
Damages induced by repair work	N/A
Use of half-joints	×

Technical approval

	TA prevent (1968)?	TA prevent (2009)?
Poor anchoring detail of top bars	✓	✓
Misplacement of bars	×	
Concrete not durable	✓	✓
Absence of shear reinforcement	×	
Absence of proper waterproofing	×	
Damages induced by repair work	N/A	
Use of half-joints	×	

Technical approval

	TA prevent (1968)?	TA prevent (2009)?
Poor anchoring detail of top bars	✓	✓
Misplacement of bars	×	
Concrete not durable	✓	✓
Absence of shear reinforcement	×	✓
Absence of proper waterproofing	×	✓
Damages induced by repair work	N/A	
Use of half-joints	×	✓

Technical approval

	TA prevent (1968)?	TA prevent (2009)?
Poor anchoring detail of top bars	✓	✓
Misplacement of bars	×	?
Concrete not durable	✓	✓
Absence of shear reinforcement	×	✓
Absence of proper waterproofing	×	✓
Damages induced by repair work	N/A	?
Use of half-joints	×	✓

Knowledge management

“The Commission recommends that the Government ensure that there be an effective surveillance of scientific intelligence processes and knowledge involving academics and top-level practitioners; this will ensure that persons responsible for designing and maintaining structures ... be kept constantly informed of new developments and changes in standards and practices”

*Montreal Commission of Inquiry
Recommendation 3*

Knowledge management

“The Minnesota Legislature should request the Federal Highway Administration to gather information on all major bridge deficiencies, as they become known, and to share the information with all state departments of transportation to assure systematic and timely incorporation of newly developed safety concerns into state bridge inspection practices”

*Minnesota Legislature Investigative Report
Recommendation 4a*

Reassessment

	TA prevent (1968)?	TA prevent (2009)?
Poor anchoring detail of top bars	✓	✓
Misplacement of bars	×	?
Concrete not durable	✓	✓
Absence of shear reinforcement	×	✓
Absence of proper waterproofing	×	✓
Damages induced by repair work	N/A	?
Use of half-joints	×	✓



Construction issues

“...the Commission is of the opinion that the best supervision practice was the one provided for in DSA’s contract for professional services, namely the full-time presence of supervisors on site”

Montreal Commission of Inquiry

Learning the lessons from bridge collapses



Minnesota
*I35W Highway
bridge*



Montreal
*de la Concorde
overpass*

Key issues

- Assumptions
- Quality of bridge management
- Vulnerable structures
- Load-carrying evaluation
- Knowledge management
- Design validation

References

www.cevc.gouv.qc.ca/userfiles/file/rapport/report_eng.pdf
Montreal Commission of Enquiry report

<http://www.nts.gov/publictn/2008/HAR0803.pdf>
Minnesota technical failure report

<http://www.commissions.leg.state.mn.us/jbc/gpm.htm>
Minnesota legislature investigative report

<http://www.nts.gov/dockets/Highway/HWY07MH024/default.htm>
Minnesota investigation information

<http://www.leg.state.mn.us/LRL/Issues/bridges.asp>
Minnesota summary of information sources

<http://www.bridgeforum.com/dir/collapse/>
Bridge forum collapse database